



Republic of the Philippines  
**CARAGA STATE UNIVERSITY**  
Ampayon, Butuan City 8600, Philippines  
Competence Service Uprightness  
**OFFICE OF THE GENERAL SERVICES**

Phone: 341-2296 loc. 246  
URL: <http://www.carsu.edu.ph>  
Email Address: [marilou.umpad08@gmail.com](mailto:marilou.umpad08@gmail.com)




## CERTIFICATE OF COMPLETION

Project Name : Ladies Dormitory  
Location : Caraga State University, Ampayon, Butuan City  
Contractor : **BN BUILDERS & CONSTRUCTION SUPPLIES**


This is to certify that the above-stated project has been satisfactorily completed on June 27, 2022, in accordance with the Plans and Specifications of the Contract based on the Final Inspection Report of the Inspectorate Team dated July 4, 2021.

This certification does not relieve the Contractor of these obligations and responsibilities in undertaking repair works on any defect or failure that may occur in any section of the project during the defect's liability period starting from the date of completion as herein stated. Neither is he relieved of his obligations and responsibilities pursuant to the provisions of R.A. 9184.

  
**ENGR. MARILOU G. UMPAD**  
Project Engineer, GSO-Director  
Administrative Officer V

  
**ANTHONY M. PENASO, Ph.D.**  
University President  
CSU, Ampayon, Butuan City

Conforme.

  
**ENGR. MARTIN C. ATAZAN**  
Authorized Managing Officer  
**BN BUILDERS & CONSTRUCTION SUPPLIES**



Republic of the Philippines  
**CARAGA STATE UNIVERSITY**  
Ampayon, Butuan City 8600, Philippines  
Competence Service Uprightness  
**OFFICE OF THE GENERAL SERVICES**

Phone: 341-2296 loc. 348  
URL: <http://www.carsu.edu.ph>  
Email Address:  
[marlou.umpad08@gmail.com](mailto:marlou.umpad08@gmail.com)





## CERTIFICATE OF COMPLETION

Project Name : Gents Dormitory  
Location : Caraga State University, Ampayon, Butuan City  
Contractor : **BN BUILDERS & CONSTRUCTION SUPPLIES**

This is to certify that the above-stated project has been satisfactorily completed on June 27, 2022, in accordance with the Plans and Specifications of the Contract based on the Final Inspection Report of the Inspectorate Team dated July 4, 2021.

This certification does not relieve the Contractor of these obligations and responsibilities in undertaking repair works on any defect or failure that may occur in any section of the project during the defect's liability period starting from the date of completion as herein stated. Neither is he relieved of his obligations and responsibilities pursuant to the provisions of R.A. 9184.

  
**ENGR. MARLOU G. UMPAD**  
Project Engineer, GSO-Director  
Administrative Officer V

  
**ANTHONY M. PENASO, Ph.D.**  
University President  
CSU, Ampayon, Butuan City

Conforme: 

**ENGR. MARTIN C. ATAZAN**  
Authorized Managing Officer  
**BN BUILDERS & CONSTRUCTION SUPPLIES**